

ELECTRICAL SAFETY FOLLOW UP INSPECTION REPORT (6TH)

Factory Name	UTAH Fashions Ltd			Note:	
Address	South Shalna, Shalna Bazar Gazipur Gazipur Dhaka Bangladesh				
FACTORY ID	9532	ELECTRICAL SAFETY INSPECTION DATES			Other Factory:
Initial Inspection Date		24/04/2014	14/09/2017	Date of 5 th Follow Up	
Report Received Date		04/12/2015	05/09/2018	Date of 6 th Follow Up	
Date of 1st Follow Up		14/10/2015		Date of 7 th Follow Up	
Date of 2nd Follow Up		02/03/2016		Date of 8 th Follow Up	
Date of 3rd Follow Up		02/03/2017		Date of 9 th Follow Up	
Date of 4th Follow Up		30/05/2017		Date of 10 th Follow Up	
Inspected by	Shamim Md Osman				

Item No	Accord Inspection Observation	Accord Action Plan (Recommendation)	Accord Time line (given in report)	Comments from Accord (After Physical Inspection)	Final Timeline (Approved timeline)	Final Action Plan (Factory)	Progress Status (On the date of inspection)	Pictorial Evidence
1	Connection is achieved with covered conductors, however the connection is not led into the building in an organized manner.	The overhead service connection shall be led into buildings via roof poles or service masts made of GI pipe having a goose neck bend at the top and installed on the outer wall.	8/21/2014	On 02/03/2017: Corrected. 400v cable replaced by 11kv cable.	'15/04/2016	Accord team verified and found corrected.	Corrected	
2	Operators and workers reported that they received training, however no documentation could be provided for confirmation.	Develop and implement an electrical safety program. Include key topics such as lock out tag out procedures, personal protective equipment requirements, etc. Reference NFPA 70e for example program requirements.	8/18/2014	Already Corrected at Accord 1st follow-up	'31/05/2015	Accord team verified and found corrected.	Corrected	

ELECTRICAL SAFETY FOLLOW UP INSPECTION REPORT (6th)

Item No	Accord Inspection Observation	Accord Action Plan (Recommendation)	Accord Time line (given in report)	Comments from Accord (After Physical Inspection)	Final Timeline (Approved timeline)	Final Action Plan (Factory)	Progress Status (On the date of inspection)	Pictorial Evidence
3	Panel boards on the 4th and 5th floors are close to the windows, allowing the ingress of water.	Provide adequate protection so that no damage is caused by the ingress of water. Panels may need to be moved, or windows permanently sealed closed.	41981	Window is sealed permanently	'31/12/2015	Accord team verified and found corrected.	Corrected	
4	Combustible materials are stored in 2nd Substation room	Remove improperly stored combustible materials from the 2nd substation room.	41919	Corrected at previous follow up.	'15/12/2015	Accord team verified and found corrected.	Corrected	
5	Generator five (23 kVA) is in a open space on the north-east corner of the main building at the entrance of the 3rd ancillary building.	Separated generator five from other occupancies in main building by 2-hour fire resistant assembly.	41828	On 02/03/2017: Corrected. Generator(23kVA) removed from mentioned location.	'15/04/2016	Accord team verified and found corrected.	Corrected	

ELECTRICAL SAFETY FOLLOW UP INSPECTION REPORT (6th)

Item No	Accord Inspection Observation	Accord Action Plan (Recommendation)	Accord Time line (given in report)	Comments from Accord (After Physical Inspection)	Final Timeline (Approved timeline)	Final Action Plan (Factory)	Progress Status (On the date of inspection)	Pictorial Evidence
6	No evidence of a documented Insulation Resistance Measurement Program	Develop an Insulation Resistance Measurement Program that ensures deterioration of insulation resistance will be identified quickly. Testing should be in compliance with International Electrical Testing Association (NETA).	41767	Already Corrected at Accord 1st follow-up	'31/07/2015	Accord team verified and found corrected.	Corrected	
7	Permanent identification was not found on multiple switchboards and/or distribution boards.	All distribution boards shall be marked "Lighting" or "Power", as the case may be, and also be marked with the voltage and number of phases of the supply.	7/21/2014	Already Corrected at Accord 1st follow-up	'31/07/2015	Accord team verified and found corrected.	Corrected	
8	No capacity information labels were found.	Label all switchboards and/or distribution boards in the factory with capacity information. The permanent label should identify the maximum voltage present in an item of equipment or within the enclosure.	41737	Already Corrected at Accord 1st follow-up	'31/07/2015	Accord team verified and found corrected.	Corrected	

ELECTRICAL SAFETY FOLLOW UP INSPECTION REPORT (6th)

Item No	Accord Inspection Observation	Accord Action Plan (Recommendation)	Accord Time line (given in report)	Comments from Accord (After Physical Inspection)	Final Timeline (Approved timeline)	Final Action Plan (Factory)	Progress Status (On the date of inspection)	Pictorial Evidence
9	Canopies of several ceiling-fans are open or broken.	Repair/replace ceiling fan canopies. Coils and wiring should be covered.	41767	Already Corrected at Accord 1st follow-up	'20/09/2015	Accord team verified and found corrected.	Corrected	
10	Switchboards on the management section at main building are placed on the floor.	Repair/Replace broken or damage switchboards. Consider moving switchboards from floor or use resistant (metal) materials for construction of covers and boxes.	41767	Corrected at previous follow up.	'15/03/2016	Accord team verified and found corrected.	Corrected	
11	Generator Five (5) (23kVA) is only grounded at one point.	Ground generator at two separate points as per Bangladesh Electricity Rules 1937, Clause 57	41737	Already Corrected at Accord 1st follow-up	'20/09/2015	Accord team verified and found corrected.	Corrected	

ELECTRICAL SAFETY FOLLOW UP INSPECTION REPORT (6th)

Item No	Accord Inspection Observation	Accord Action Plan (Recommendation)	Accord Time line (given in report)	Comments from Accord (After Physical Inspection)	Final Timeline (Approved timeline)	Final Action Plan (Factory)	Progress Status (On the date of inspection)	Pictorial Evidence
12	The main substation room is in compliance, however the 2nd substation does not have adequate illumination.	Provide additional light fixtures to increase illumination levels provided in the BNBC.	7/22/2014	Already Corrected at Accord 1st follow-up	'20/09/2015	Accord team verified and found corrected.	Corrected	
13	The 2nd substation for the REB supply is dirty and filled with junk materials.	Remove all dirt, debris, lint, water, oil, and improperly stored materials from the substation room.	7/22/2014	Already Corrected at Accord 1st follow-up	'20/09/2015	Accord team verified and found corrected.	Corrected	
14	2nd Substation room is not adequately ventilated.	Provide means of ventilation for the substation room. Consult a qualified electrical engineer to determine the required ventilation rates based on the installed equipment.	41767	Corrected at previous follow up.	'31/12/2015	Accord team verified and found corrected.	Corrected	

ELECTRICAL SAFETY FOLLOW UP INSPECTION REPORT (6th)

Item No	Accord Inspection Observation	Accord Action Plan (Recommendation)	Accord Time line (given in report)	Comments from Accord (After Physical Inspection)	Final Timeline (Approved timeline)	Final Action Plan (Factory)	Progress Status (On the date of inspection)	Pictorial Evidence
15	Cable at north-east corner of the main building not secured within rigid conduit.	All cabling and wiring must be supported and covered for safety. Install cable trays/ladder/risers or rigid conduits for the noted cabling to prevent from mechanical stress and physical damages. Conduits must be firmly affixed to the walls.	41767	Corrected at previous follow up.	'01/01/2016	Accord team verified and found corrected.	Corrected	
16	No signage was found indicating the prohibition of light fixtures without protective covers	Light fixtures without protective covers (otherwise known as naked lights) shall not be allowed in storage areas or in any area where the Inspector of the Factories Rules (1.6.3.7) Part 53 disallows these fixtures. Install signs posted in Bengali and English, indicating this prohibition at all entrances to these areas.	7/21/2014	Corrected at previous follow up.	'15/12/2015	Accord team verified and found corrected.	Corrected	
17	New Finding: Hot spots at terminations inside panel. Thermo graphic inspection record is available, but it is out of date	Arrange periodic inspection & thermal scan at least twice in a year to identify the overloading, loose connection, unbalanced load which may cause the excessive heat-rise and take action accordingly. However, immediately correct such points.	1 Month	On 02/03/2017: Corrected.	'21/06/2016	Accord team verified and found corrected.	Corrected	

ELECTRICAL SAFETY FOLLOW UP INSPECTION REPORT (6th)

Item No	Accord Inspection Observation	Accord Action Plan (Recommendation)	Accord Time line (given in report)	Comments from Accord (After Physical Inspection)	Final Timeline (Approved timeline)	Final Action Plan (Factory)	Progress Status (On the date of inspection)	Pictorial Evidence
18	New Finding: Lightning Protections System (LPS) is inadequate for the factory whether appropriate drawing is available in the factory	Install LPS for your factory according to the drawing which is available in the factory	2 Months	On 02/03/2017: Corrected.	'15/05/2016	Accord team verified and found corrected.	Corrected	
19	New Finding: Electrical Single Line Diagram (SLD) has inadequate information which has no effectiveness.	Prepare SLD more informative thus anyone can understand it.	2 months	On 02/03/2017: Not Corrected. On 30/05/2017: Not corrected. On 14/09/2017: Not corrected. Found as built in most of the place, but all place cannot be access due to retrofitting work. On 05/09/2018: Corrected.	'15/05/2016	DONE, Already we have prepared SLD as per ACCORD guideline.	Corrected	 AS BUILT 05.09.2018
20	New Finding: Power cables entering or exiting from Distribution board/panel are not properly fixed.	Power cables entering or exiting from distribution board/panel must be fixed through Panel base/top plate using proper sized cable glands (metal/PVC).	1 Month	On 30/05/2017: Not corrected. On 14/09/2017: Not corrected. In few places cables found without support. On 05/09/2018: Corrected.	'15/04/2017	DONE, Already we have fixed all power cables entering and exiting from distribution board/panel with using proper size cable glands.	Corrected	 05.09.2018

ELECTRICAL SAFETY FOLLOW UP INSPECTION REPORT (6th)

Item No	Accord Inspection Observation	Accord Action Plan (Recommendation)	Accord Time line (given in report)	Comments from Accord (After Physical Inspection)	Final Timeline (Approved timeline)	Final Action Plan (Factory)	Progress Status (On the date of inspection)	Pictorial Evidence																																																																																																																																																																																																																																
21	New Finding: Insulation resistance record (cable information) doesn't match with field	Field information must be reflected in the record and significantly lower sized cables' record shall be avoided	1 Month	On 14/09/2017: Not corrected. Insulation test found, but cable size is not mentioned in the report. On 05/09/2018: Corrected.	'10/07/2017	DONE, Already we have arranged Insulation test with cable size mentioned in the report.	Corrected	<table border="1"> <thead> <tr> <th>S/A NO</th> <th>Date</th> <th>From</th> <th>To</th> <th>Outgoing MCCB</th> <th>Cable Size (RM)</th> <th>R - V</th> <th>Y - B</th> <th>B - R</th> <th>R - N</th> <th>Y - H</th> <th>B - H</th> <th>R - E</th> <th>Y - E</th> </tr> </thead> <tbody> <tr><td>1</td><td>05.01.2018</td><td>CO-01</td><td>DB-06</td><td>100A MCCB</td><td>4*12*150 RM</td><td>1350</td><td>1209</td><td>1217</td><td>1200</td><td>1307</td><td>1219</td><td>1099</td><td>1050</td></tr> <tr><td>2</td><td>05.01.2018</td><td>CO-01</td><td>DB-05</td><td>100A MCCB</td><td>4*4C*95 RM</td><td>1350</td><td>1160</td><td>1172</td><td>1145</td><td>1335</td><td>1141</td><td>950</td><td>950</td></tr> <tr><td>3</td><td>05.01.2018</td><td>CO-01</td><td>DB-09</td><td>100A MCCB</td><td>4*4C*70 RM</td><td>1050</td><td>1010</td><td>1045</td><td>1037</td><td>1049</td><td>1030</td><td>900</td><td>900</td></tr> <tr><td>4</td><td>05.01.2018</td><td>CO-01</td><td>DB-10</td><td>100A MCCB</td><td>4*12*95 RM</td><td>1100</td><td>1135</td><td>1120</td><td>1140</td><td>1150</td><td>1139</td><td>1009</td><td>1037</td></tr> <tr><td>5</td><td>05.01.2018</td><td>CO-01</td><td>DB-11</td><td>100A MCCB</td><td>4*4C*70 RM</td><td>755</td><td>755</td><td>749</td><td>740</td><td>749</td><td>760</td><td>680</td><td>689</td></tr> <tr><td>6</td><td>05.01.2018</td><td>CO-01</td><td>DB-16</td><td>400A MCCB</td><td>8*12*95 RM</td><td>1350</td><td>1159</td><td>1140</td><td>1130</td><td>1130</td><td>1100</td><td>1050</td><td>1001</td></tr> <tr><td>7</td><td>05.01.2018</td><td>CO-01</td><td>DB-18</td><td>31A MCB</td><td>4*12*15 RM</td><td>660</td><td>656</td><td>641</td><td>621</td><td>507</td><td>583</td><td>551</td><td>529</td></tr> <tr><td>8</td><td>14.01.2018</td><td>CO-01</td><td>DB-03</td><td>400A MCCB</td><td>8*12*130 RM</td><td>1300</td><td>1090</td><td>1070</td><td>1080</td><td>1200</td><td>1178</td><td>1100</td><td>1070</td></tr> <tr><td>9</td><td>05.01.2018</td><td>CO-02</td><td>DB-02</td><td>100A MCCB</td><td>4*4C*70 RM</td><td>1010</td><td>1000</td><td>1017</td><td>1000</td><td>1009</td><td>1005</td><td>909</td><td>925</td></tr> <tr><td>10</td><td>05.01.2018</td><td>CO-02</td><td>DB-03</td><td>100A MCCB</td><td>4*4C*70 RM</td><td>1008</td><td>1015</td><td>1019</td><td>1009</td><td>1001</td><td>999</td><td>907</td><td>906</td></tr> <tr><td>11</td><td>05.01.2018</td><td>CO-02</td><td>DB-04</td><td>100A MCCB</td><td>4*4C*95 RM</td><td>1120</td><td>1125</td><td>1150</td><td>1165</td><td>1107</td><td>1109</td><td>1017</td><td>1025</td></tr> <tr><td>12</td><td>05.01.2018</td><td>CO-02</td><td>DB-05</td><td>100A MCCB</td><td>4*4C*95 RM</td><td>1165</td><td>1160</td><td>1125</td><td>1100</td><td>1107</td><td>1109</td><td>1015</td><td>1019</td></tr> <tr><td>13</td><td>05.01.2018</td><td>CO-03</td><td>DB-20</td><td>100A MCCB</td><td>4*12*35 RM</td><td>1195</td><td>1170</td><td>1185</td><td>1180</td><td>1160</td><td>1200</td><td>1140</td><td>1090</td></tr> <tr><td>14</td><td>05.01.2018</td><td>CO-03</td><td>DB-25</td><td>100A MCCB</td><td>4*12*35 RM</td><td>1220</td><td>1060</td><td>1210</td><td>1118</td><td>1120</td><td>1130</td><td>1110</td><td>1100</td></tr> <tr><td>15</td><td>05.01.2018</td><td>CO-03</td><td>DB-27</td><td>100A MCCB</td><td>4*4C*35 RM</td><td>1200</td><td>1170</td><td>1150</td><td>1165</td><td>1150</td><td>1140</td><td>1080</td><td>1080</td></tr> </tbody> </table> <p>05.09.2018 By Executive Electrical</p>	S/A NO	Date	From	To	Outgoing MCCB	Cable Size (RM)	R - V	Y - B	B - R	R - N	Y - H	B - H	R - E	Y - E	1	05.01.2018	CO-01	DB-06	100A MCCB	4*12*150 RM	1350	1209	1217	1200	1307	1219	1099	1050	2	05.01.2018	CO-01	DB-05	100A MCCB	4*4C*95 RM	1350	1160	1172	1145	1335	1141	950	950	3	05.01.2018	CO-01	DB-09	100A MCCB	4*4C*70 RM	1050	1010	1045	1037	1049	1030	900	900	4	05.01.2018	CO-01	DB-10	100A MCCB	4*12*95 RM	1100	1135	1120	1140	1150	1139	1009	1037	5	05.01.2018	CO-01	DB-11	100A MCCB	4*4C*70 RM	755	755	749	740	749	760	680	689	6	05.01.2018	CO-01	DB-16	400A MCCB	8*12*95 RM	1350	1159	1140	1130	1130	1100	1050	1001	7	05.01.2018	CO-01	DB-18	31A MCB	4*12*15 RM	660	656	641	621	507	583	551	529	8	14.01.2018	CO-01	DB-03	400A MCCB	8*12*130 RM	1300	1090	1070	1080	1200	1178	1100	1070	9	05.01.2018	CO-02	DB-02	100A MCCB	4*4C*70 RM	1010	1000	1017	1000	1009	1005	909	925	10	05.01.2018	CO-02	DB-03	100A MCCB	4*4C*70 RM	1008	1015	1019	1009	1001	999	907	906	11	05.01.2018	CO-02	DB-04	100A MCCB	4*4C*95 RM	1120	1125	1150	1165	1107	1109	1017	1025	12	05.01.2018	CO-02	DB-05	100A MCCB	4*4C*95 RM	1165	1160	1125	1100	1107	1109	1015	1019	13	05.01.2018	CO-03	DB-20	100A MCCB	4*12*35 RM	1195	1170	1185	1180	1160	1200	1140	1090	14	05.01.2018	CO-03	DB-25	100A MCCB	4*12*35 RM	1220	1060	1210	1118	1120	1130	1110	1100	15	05.01.2018	CO-03	DB-27	100A MCCB	4*4C*35 RM	1200	1170	1150	1165	1150	1140	1080	1080
S/A NO	Date	From	To	Outgoing MCCB	Cable Size (RM)	R - V	Y - B	B - R	R - N	Y - H	B - H	R - E	Y - E																																																																																																																																																																																																																											
1	05.01.2018	CO-01	DB-06	100A MCCB	4*12*150 RM	1350	1209	1217	1200	1307	1219	1099	1050																																																																																																																																																																																																																											
2	05.01.2018	CO-01	DB-05	100A MCCB	4*4C*95 RM	1350	1160	1172	1145	1335	1141	950	950																																																																																																																																																																																																																											
3	05.01.2018	CO-01	DB-09	100A MCCB	4*4C*70 RM	1050	1010	1045	1037	1049	1030	900	900																																																																																																																																																																																																																											
4	05.01.2018	CO-01	DB-10	100A MCCB	4*12*95 RM	1100	1135	1120	1140	1150	1139	1009	1037																																																																																																																																																																																																																											
5	05.01.2018	CO-01	DB-11	100A MCCB	4*4C*70 RM	755	755	749	740	749	760	680	689																																																																																																																																																																																																																											
6	05.01.2018	CO-01	DB-16	400A MCCB	8*12*95 RM	1350	1159	1140	1130	1130	1100	1050	1001																																																																																																																																																																																																																											
7	05.01.2018	CO-01	DB-18	31A MCB	4*12*15 RM	660	656	641	621	507	583	551	529																																																																																																																																																																																																																											
8	14.01.2018	CO-01	DB-03	400A MCCB	8*12*130 RM	1300	1090	1070	1080	1200	1178	1100	1070																																																																																																																																																																																																																											
9	05.01.2018	CO-02	DB-02	100A MCCB	4*4C*70 RM	1010	1000	1017	1000	1009	1005	909	925																																																																																																																																																																																																																											
10	05.01.2018	CO-02	DB-03	100A MCCB	4*4C*70 RM	1008	1015	1019	1009	1001	999	907	906																																																																																																																																																																																																																											
11	05.01.2018	CO-02	DB-04	100A MCCB	4*4C*95 RM	1120	1125	1150	1165	1107	1109	1017	1025																																																																																																																																																																																																																											
12	05.01.2018	CO-02	DB-05	100A MCCB	4*4C*95 RM	1165	1160	1125	1100	1107	1109	1015	1019																																																																																																																																																																																																																											
13	05.01.2018	CO-03	DB-20	100A MCCB	4*12*35 RM	1195	1170	1185	1180	1160	1200	1140	1090																																																																																																																																																																																																																											
14	05.01.2018	CO-03	DB-25	100A MCCB	4*12*35 RM	1220	1060	1210	1118	1120	1130	1110	1100																																																																																																																																																																																																																											
15	05.01.2018	CO-03	DB-27	100A MCCB	4*4C*35 RM	1200	1170	1150	1165	1150	1140	1080	1080																																																																																																																																																																																																																											
22	New Finding: LPS not maintained regularly. Connectors are rusted. Earth pits resistance test report for LPS is not prepared properly. Air terminal spacing is not accurate & all metals are not bonded properly	Rusted/damaged joints, air terminals, conductor shall be cleaned/replaced. LPS shall be maintained regularly for loosened joints, damaged/broken air terminals & bonding. All earthing systems for LPS shall be tested for resistance on any dry day not less than once in every two years. A record of every earth test made and the result shall be kept for not less than two years and shall be available to the Inspector when required. Air terminal spacing & bonding shall be done properly	1 Month	On 14/09/2017: Not corrected. Air terminal spacing is found ok, but rest of work is not done yet. On 05/09/2018: Corrected.	'10/07/2017	DONE, Already we have installed LPS as per ACCORD guideline	Corrected	<p>05.09.2018</p>																																																																																																																																																																																																																																

ELECTRICAL SAFETY FOLLOW UP INSPECTION REPORT (6th)

Item No	Accord Inspection Observation	Accord Action Plan (Recommendation)	Accord Time line (given in report)	Comments from Accord (After Physical Inspection)	Final Timeline (Approved timeline)	Final Action Plan (Factory)	Progress Status (On the date of inspection)	Pictorial Evidence
23	New Finding: Power cables are bent excessively Indicator lights are mounted without control device.	Power cables must be installed as straight as possible; in unavoidable case, not less than 135-degree bending can be allowed. Indicator lights should be connected by control device such as rated fuse or MCB.	1 Month	On 14/09/2017: Not Corrected. Indicator is provided with protection. Cable bending is not removed yet. On 05/09/2018: Corrected.	'10/07/2017	DOEN, Already we have taken necessary corrective action	Corrected	
24	New Finding: Instruction for CPR (Cardiopulmonary Resuscitation) or Electrical shock restoration is not present	CPR instruction shall be hanged near all electrical installations (LT panel, MDB, FDB, DB, SDB) at visible location	1 Month	On 14/09/2017: Corrected.	'10/07/2017	Corrected	Corrected	
25	New Finding: Cable channel/duct terminals are left open for ingress of lint, dust or fluffs.	cable ducts must be properly sealed to avoid ingress of any foreign particles.	1 Month	On 14/09/2017: Not Corrected. Still few cable ducts is not covered yet. On 05/09/2018: Corrected.	'10/07/2017	DONE, Already we have provided cable ducts in all electrical channel.	Corrected	

Item No	Accord Inspection Observation	Accord Action Plan (Recommendation)	Accord Time line (given in report)	Comments from Accord (After Physical Inspection)	Final Timeline (Approved timeline)	Final Action Plan (Factory)	Progress Status (On the date of inspection)	Pictorial Evidence
26	<p>New Finding: Loop connection has been used powering multiple circuits through MCB/MCCBs.</p> <p>Multiple cables connected/terminated at the bus bar using single cable lug.</p>	<p>No loop connection shall be used; each single cable shall be terminated using cable lug (flat/I) at each terminal. Combo bus bar may be used (but incoming cable size must meet the rated capacity)</p> <p>Each power cable must be terminated at any point using single cable lug.</p>	1 Month	<p>On 14/09/2017: Not Corrected. Looping connection has been removed. Multiple connections found on those breaker installed on cable duct</p> <p>On 05/09/2018: Corrected.</p>	'10/07/2017	DONE, Already we have taken necessary corrective action	Corrected	

ELECTRICAL SAFETY FOLLOW UP INSPECTION REPORT (6th)

Item No	Accord Inspection Observation	Accord Action Plan (Recommendation)	Accord Time line (given in report)	Comments from Accord (After Physical Inspection)	Final Timeline (Approved timeline)	Final Action Plan (Factory)	Progress Status (On the date of inspection)	Pictorial Evidence
27	<p>New Finding: Panel/Distribution boxes are inaccessible or cannot be opened to perform any maintenance work.</p> <p>Inadequate rubber (insulation) mat at the working area of distribution board/panel.</p>	<p>Each electrical distribution board/panel must be easily accessible. In case of height its top shall not be higher than 2m from base; and door opening shall be at least 90 degree.</p> <p>Electrical insulation (not less than 3 mm thick in case of rubber mat) at the working area of each electrical installation (Transformer/LT panel/MDB/DB/SDB/ other manual operated machineries) must be ensured.</p>	1 Month	<p>On 14/09/2017: Not Corrected. Rubber mat is provided in front of panel, but there are many inaccessible panel.</p> <p>On 05/09/2018: Corrected.</p>	10/07/2017	<p>DONE / CORRECTED</p> <p>Already we have taken corrective actions and now made all the panels accessible . Please see the attached evidence</p>	Corrected	
28	<p>New Finding: MCCBs are not adjusted per load demand.</p>	<p>All the MCCBs must be adjusted per cable current ampacity/load current; if adjustment is not possible, replacement will be the only way.</p>	1 Month	<p>On 14/09/2017: Not Corrected. Higher size breaker is still found in few places.</p> <p>On 05/09/2018: Corrected.</p>	10/07/2017	<p>DONE, Already we have removed all oversize circuit brackers.</p>	Corrected	



ELECTRICAL SAFETY FOLLOW UP INSPECTION REPORT (6th)

Item No	Accord Inspection Observation	Accord Action Plan (Recommendation)	Accord Time line (given in report)	Comments from Accord (After Physical Inspection)	Final Timeline (Approved timeline)	Final Action Plan (Factory)	Progress Status (On the date of inspection)	Pictorial Evidence
29	New Finding: Cables in service are joined (splicing) between terminations.	Splicing in the power cables shall be avoided; in unavoidable cases splicing, must be made following proper guidance.	1 Month	On 14/09/2017: Not Corrected. Only inside the panel, corrective action has been taken. There are many outside the panel yet to correct. On 05/09/2018: Corrected.	'10/07/2017	DONE, Already we have taken necessary corrective action of all inside and outside panel	Corrected	
30	New Finding: Phase barrier/separators are missing in MCCBs Power bus bars are installed congested	Phases must be separated by insulator (a rubber type no-flammable materials shall be used for it) Power bus bar must be installed with adequate clearance (not less than 2.5 inch for LV) between two bars.	1 Month	On 14/09/2017: Not Corrected. Phase separator has been provided between circuit breaker in few places, but busbars are still found congested without insulation. On 05/09/2018: Corrected.	'10/07/2017	DONE, Already we have installed Phase barrier/separators in MCCBs	Corrected	
31	New Finding: Power cable is buried in the concrete floor	Power cables must not be buried in the concrete. A cable trench shall be constructed or routing power cables.	1 Month	On 14/09/2017: Not Corrected. Provide cable protection in floor penetration area. On 05/09/2018: Corrected.	'10/07/2017	DONE, Already we have taken necessary corrective action as required.	Corrected	



ELECTRICAL SAFETY FOLLOW UP INSPECTION REPORT (6th)

Item No	Accord Inspection Observation	Accord Action Plan (Recommendation)	Accord Time line (given in report)	Comments from Accord (After Physical Inspection)	Final Timeline (Approved timeline)	Final Action Plan (Factory)	Progress Status (On the date of inspection)	Pictorial Evidence
32	New Finding: Hot spots have been observed at some points.	Thermography survey must be done and recorded at least twice in a year. Hot spots must be removed.	1 Month	On 14/09/2017: Corrected.	'10/07/2017	Corrected	Corrected	
33	New Finding: Earth connections for different electrical installation are not segregated HT & LT ECC connections are not segregated	All the earth connections (transformer, generator and electrical systems) must be segregated and clearly marked (for TT earthing system).	1 Month	On 14/09/2017: Not Corrected. Identification is not completed yet. Prepared an earthing layout and ensure a required number of earthing is connected to equipment. On 05/09/2018: Corrected.	'10/07/2017	DONE, We have installed segregation and marking of earth connections (transformer, generator and electrical systems) (for TT earthing system).	Corrected	

ELECTRICAL SAFETY FOLLOW UP INSPECTION REPORT (6th)

Item No	Accord Inspection Observation	Accord Action Plan (Recommendation)	Accord Time line (given in report)	Comments from Accord (After Physical Inspection)	Final Timeline (Approved timeline)	Final Action Plan (Factory)	Progress Status (On the date of inspection)	Pictorial Evidence
34	New Finding: Earth pits are not identifiable	Each earth pit shall be properly identifiable and marked for periodic maintenance.	1 Month	On 14/09/2017: Not Corrected. Identification is done inside the room & on the busbar only. Provide identification on the earth pit location. On 05/09/2018: Corrected.	'10/07/2017	DONE, We have provided identification marking of all earth pit and performing periodic maintenance.	Corrected	
35	<p>New Finding: Floor in generator room is wet.</p> <p>Generator output cables (laid on floor) are not protected and supported</p> <p>Generator output box has openings</p> <p>Generator may be damaged by ingress of rain water & leakage of steam line</p>	<p>Surrounding area of generator room should be clean & dry to avoid any unexpected accident.</p> <p>Service cables from generator must be supported at its own breaker's terminal and with cable tray.</p> <p>Unwanted openings shall be sealed properly.</p> <p>Steps shall be taken to relocate the steam line from generator room & stop ingress of rain water</p>	1 Month	On 14/09/2017: Not Corrected. Generator room is not completely accessible due to massive retrofitting work. On 05/09/2018: Corrected.	'10/07/2017	DONE, We have been completed retrofitting work. Now, Easy access to Generator room for authorized personnel	Corrected	

ELECTRICAL SAFETY FOLLOW UP INSPECTION REPORT (6th)

Item No	Accord Inspection Observation	Accord Action Plan (Recommendation)	Accord Time line (given in report)	Comments from Accord (After Physical Inspection)	Final Timeline (Approved timeline)	Final Action Plan (Factory)	Progress Status (On the date of inspection)	Pictorial Evidence
36	New Finding: Power socket is kept on floor	Power socket shall be install at minimum 200mm above the floor with a rigid support.	1 Month	On 05/09/2018: Corrected.	'25/09/2017	DONE / CORRECTED ----- Already we have installed all power socket at minimum 200mm above the floor with a rigid support. Please see the attached evidence	Corrected	
37	New Finding: Circuit is drawn from bus bar without any protective means	Each electrical circuit must be drawn from distribution board busbar using a proper type protection arrangement (MCCB/MCB).	2 Months	On 05/09/2018: Corrected.	'25/10/2017	DONE, Already we have arranged all electrical circuit drawn from distribution board busbar using a proper type protection (MCCB/MCB).	Corrected	
38	New Finding: IP rating of the Panel enclosure installed outdoor is not compatible with the surrounding environment.	Panel board installed exposed to weather, to drip or in abnormally moist atmosphere, the outer casing shall be weather proof and shall be provided with glands or bushings or adapted to receive screwed conduit. IP rating of panel board for outdoor installation shall be according to the surrounding environment.	1 Month	On 05/09/2018: Corrected. The panel has been removed.	'25/09/2017	DONE, Corrective action taken	Corrected	

Item No	Accord Inspection Observation	Accord Action Plan (Recommendation)	Accord Time line (given in report)	Comments from Accord (After Physical Inspection)	Final Timeline (Approved timeline)	Final Action Plan (Factory)	Progress Status (On the date of inspection)	Pictorial Evidence
39	New Finding: The substation room (equipment rated 1200A or more) does not have a continuous and unobstructed way of egress travel.	The room shall have an entrance to and egress from (2 ft. X 6 ½ ft.) at each end of the working space if its equipment is rated 1200A or more and over 6ft wide. The doors(with panic hardware) need to be opened in the direction of egress if the door is located less than 25ft from the nearest edge of the working space. (The room shall have only one entrance if the working space depth is double, and the equipment located no closer than the required working space from the edge of the equipment)	2 Months	On 05/09/2018: Corrected.	'25/10/2017	DONE, Already we have taken necessary corrective action as per ACCORD guideline.	Corrected	 
40	New Finding: MCCB is installed without any enclosure	Each MCCB/MCB must be enclosed by proper type material. the material must not be more than 18 SWG graded.	1 Month	On 05/09/2018: Corrected.	'25/09/2017	Already we have installed MCCB with proper materials	Corrected	

ELECTRICAL SAFETY FOLLOW UP INSPECTION REPORT (6th)

Item No	Accord Inspection Observation	Accord Action Plan (Recommendation)	Accord Time line (given in report)	Comments from Accord (After Physical Inspection)	Final Timeline (Approved timeline)	Final Action Plan (Factory)	Progress Status (On the date of inspection)	Pictorial Evidence
41	New Finding: Power Cables run through flexible conduit without proper support.	Power cables must be supported by cable tray/ ladder- where needed. Use rigid conduit where there is a chance of cable damage.	1 Month	On 05/09/2018: Corrected.	'25/09/2017	Already we have installed cable tray/ laddeer for power cable supporting.	Corrected	